


OCTOBER 2018

53 WELLS SAMPLED

53 WELLS - VINYL CHLORIDE NOT DETECTED

0 WELLS - VINYL CHLORIDE DETECTED AT OR BELOW HEALTH RISK LIMIT

0 WELLS - VINYL CHLORIDE DETECTED ABOVE HEALTH RISK LIMIT (0.2 µg/L)



LEGEND

- ND** VINYL CHLORIDE NOT DETECTED (DETECTION LIMIT = 0.18 µg/L)
- ND/ND** DUPLICATE SAMPLE RESULT
- NS** NOT SAMPLED (NO RESPONSE/DECLINED/WATER OFF)
-  CONNECTED TO MUNICIPAL WATER SUPPLY
-  GEOGRAPHIC AREAS

- # RP** REPLACEMENT WELL INSTALLED BY RPs (PRAIRIE DU CHIEN AQUIFER) [OLD WELL ABANDONED]
- # RP-J** REPLACEMENT WELL INSTALLED BY RPs (EXTENDED INTO JORDAN AQUIFER AT HOMEOWNERS REQUEST/EXPENSE) [OLD WELL ABANDONED]
- # H-J** NEW WELL INSTALLED BY HOMEOWNER (JORDAN AQUIFER) [OLD WELL ABANDONED]
- *** CONVERTED RESIDENTIAL MONITORING WELL LOCATION




figure 1
VINYL CHLORIDE CONCENTRATIONS
 (OCTOBER 2018)
 North Oaks, Minnesota